

## ABSTRACT OF THE DISCLOSURE

A method of calibrating a gauge in particular for the measurement of film thickness, uses a calibration variable to compensate for short term changes in probe tip condition, instead of a constant value. A calibration constant is based only on the dielectric constant for a coating such as lacquer, and is independent of the probe tip variable.